

# Linear Transformations in Machines

Day 6



# ILOs – Day6

- Understand the need for linear transformations in electric machines
- List the pre-requisites of such transformations
- Perform one such sample transformation (displaced brush axis)

# Why Transformation?

- **Primitive (basic) 2-pole machine**

- Can be shown to be equivalent to any rotating machine
- The rotor coils are fitted with brush and commutator
- The rotor magnetic field is stationary (both in time and space) – due to the presence of brush and commutator



# Why Transformation?

---

- **Primitive (basic) 2-pole machine**
  - Can be shown to be equivalent to any rotating machine
  - The rotor coils are fitted with brush and commutator
  - The rotor magnetic field is stationary (both in time and space) – due to the presence of brush and commutator
- **These conditions are most closely met by:**
  - DC machine
    - They have brush and commutator
    - Hence their rotor magnetic field is stationary both in time and space
- **DC machines are most closely equivalent to the primitive machine with appropriate number of coils in each of the fixed axes depending on type of the DC machine**

# Why Transformation?


---

- Many rotating machines are poly-phase AC machines (induction, synchronous)
- Their construction is different from that of the primitive machine
  - They do not have brush and commutator
  - They have polyphase rotating winding in rotor
  - They have polyphase stationary winding in stator
  - Their rotor magnetic field is both time and space varying
- So they can not be directly made equivalent to the primitive machine
- **However, in those cases also, primitive machine concept can be used for analysis, provided:**
  - The rotating polyphase rotor coils and stationary polyphase stator coils can be suitably represented by the  $d$ - $q$  axes coils of the primitive machine
  - Such an equivalent representation is termed as “*Transformation*”

# What is Transformation?

---

- The process of replacing one set of variables by another set of variables for equivalent representation electrical machines is called *winding transformation* or simply *transformation*.
  - Since DC machines resemble the primitive machine structure directly, no transformation is necessary
  - Polyphase machines, however, need such transformations so that they can be fit into the primitive machine model and analyzed



# Linear Transformation

---

- The process of transformation between old and new set of variables and *vice versa* is described by linear equations
  - Transformations are generally done to:
    - Simply the solution process
    - Reduce number of variables to be dealt with
    - Reduce number of equations to be solved
- *Transformation matrix* is used to show the relationship between old and new variables in *transformation equations*:

$$[\text{Old variables}] = [\text{Transformation matrix}] [\text{New variables}]$$

or,

$$[\text{New variables}] = [\text{Transformation matrix}] [\text{Old variables}]$$

# Linear Transformation


---

- **Examples of linear transformation:**
  - Logarithmic & anti-logarithmic transformations
  - Laplace & inverse Laplace transformations (time to  $s$  domain)
  - Symmetrical components in power system fault analysis
  - Referring primary quantities to secondary or secondary quantities to primary in a transformer



# Why Transformation in machines?


- Fitting polyphase machine models to generalized machine model
- Reducing number of equations to be solved
- 3-phase machine require three voltage equations to be solved
- But its generalized model has only two coils, so only two equations to be solved
- Magnetic coupling between the three windings of a 3-phase machine makes the circuit equations much more complicated
- In the generalized 2-axis model, the two coils along  $d$  and  $q$  axes are magnetically independent since they are at  $90^\circ$



# Pre-requisites of Transformation

---

- Voltage and current transformation matrices can be different
- But they should be so related that the total; power remain invariant between the old and the new (transformed) system [ **power invariance** ]
- Current transformations should be done in such a way that MMF must remain same (magnitude and direction) in the new set as compared to the old set.
- In other words, MMF produced in the two cases (pre and post transformation) must be time and space invariant



# Different Transformations in machines

---

Transformation from a displaced brush axis



Transformation from 3-phase to 2-phase ( $a-b-c$  to  $\alpha-\beta$ )

Transformation from rotating axes to stationary axes ( $\alpha-\beta-0$  to  $d-q-0$ )

# Transformations from a displaced brush axis

# Transformations from a displaced brush axis


- The generalized 2-pole structure, the brush axes are assumed to coincide with the  $d$ - and  $q$ - axes



# Transformations from a displaced brush axis



---

- The generalized 2-pole structure, the brush axes are assumed to coincide with the  $d$ - and  $q$ - axes
- However, a DC machine may have its brushes displaced from  $d$ - or  $q$ - axes
- In such a case, a transformation is necessary from brush axes to  $d$ - $q$  axes





# Transformations from a displaced brush axis

- Let, one such set of brush  $AA'$  is shifted by an angle  $\alpha$  w.r.t. the  $d$ -axis
- The armature coil thus can be assumed to be located along the  $AA'$  axis



# Transformations from a displaced brush axis



- Let, one such set of brush  $AA'$  is shifted by an angle  $\alpha$  w.r.t. the  $d$ -axis
- The armature coil thus can be assumed to be located along the  $AA'$  axis
- The armature coil develops an MMF  $F_a$  along the brush axis





# Transformations from a displaced brush axis



- Let, one such set of brush  $AA'$  is shifted by an angle  $\alpha$  w.r.t. the  $d$ -axis
- The armature coil thus can be assumed to be located along the  $AA'$  axis
- The armature coil develops an MMF  $F_a$  along the brush axis
- This MMF  $F_a$  can be resolved in two orthogonal components



# Transformations from a displaced brush axis

- $F_d$  along d-axis and  $F_q$  along q-axis

$$F_d = F_a \cos \alpha \quad F_q = F_a \sin \alpha$$



# Transformations from a displaced brush axis

- $F_d$  along d-axis and  $F_q$  along q-axis

$$F_d = F_a \cos \alpha \quad F_q = F_a \sin \alpha$$


- These two component MMFs ( $F_d$  and  $F_q$ ) can be assumed to be developed by two equivalent coils along  $d$ -, and  $q$ -axes
- Each having same number of turns  $N$  as the armature coil
- Thus, we have the current relations:

$$Ni_d = Ni_a \cos \alpha$$

or,  $i_d = i_a \cos \alpha$

$$Ni_q = Ni_a \sin \alpha$$

or,  $i_q = i_a \sin \alpha$



# Transformations from a displaced brush axis

- $F_d$  along d-axis and  $F_q$  along q-axis

$$F_d = F_a \cos \alpha \quad F_q = F_a \sin \alpha$$

- These two component MMFs ( $F_d$  and  $F_q$ ) can be assumed to be developed by two equivalent coils along d-, and q-axes
- Each having same number of turns  $N$  as the armature coil
- Thus, we have the current relations:


$$Ni_d = Ni_a \cos \alpha$$

or,  $i_d = i_a \cos \alpha$

$$Ni_q = Ni_a \sin \alpha$$



or,  $i_q = i_a \sin \alpha$

Thus, we have the equivalent **(transformed)** component currents  $i_d$  and  $i_q$  in d- and q-axis coils respectively



# Transformations from a displaced brush axis

- In addition to the brush pair AA', let us assume another pair of brushes BB' that makes an angle  $\beta$  w.r.t. the  $q$ -axis
- Armature coil along BB' produces an MMF  $F_b$  that can also be resolved in two orthogonal components along  $d$ - and  $q$ -axes



# Transformations from a displaced brush axis

- Let us combine the effects of components of  $F_a$  and  $F_b$  along  $d$ - and  $q$ -axes

$$F_d = F_a \cos \alpha - F_b \sin \beta$$



$$F_q = F_a \sin \alpha + F_b \cos \beta$$

- Assuming equal number turns in the main armature coils and also in the equivalent  $d$ - and  $q$ - axes coils, we have the transformed current relations:

$$i_d = i_a \cos \alpha - i_b \sin \beta$$

$$i_q = i_a \sin \alpha + i_b \cos \beta$$

Thus, we have the equivalent (**transformed**) component currents  $i_d$  and  $i_q$  in  $d$ - and  $q$ -axis coils respectively



# Transformations from a displaced brush axis

- Transformation equations

$$i_d = i_a \cos \alpha - i_b \sin \beta$$

$$i_q = i_a \sin \alpha + i_b \cos \beta$$

- In matrix form:

$$\begin{bmatrix} i_d \\ i_q \end{bmatrix} = \begin{bmatrix} \cos \alpha & -\sin \beta \\ \sin \alpha & \cos \beta \end{bmatrix} \begin{bmatrix} i_a \\ i_b \end{bmatrix}$$

New variables

Old variables

Transformation matrix

