M.E. MECHANICAL ENGINEERING FIRST YEAR SECOND SEMESTER - 2019

ADVANCED METHODS OF MACHINING

Time: Three Hours

Full Marks: 100

Answer any *five* questions.

Assume relevant data, if necessary.

- 1. a) In brief explain the process of CHM. Give a schematic schedule in PCM process.
 - b) Write the classification of the maskants and mention there uses.
 - c) Explain the ECG process. Give necessary sketch.

8+6+6

- a) Discuss the tool design for ECM process.
 - b) The geometry of a work piece surface with single curvature is given by the equation y=10+0.3x-0.05x² where x and y are in cm. The process data are Applied potential = 15 V

 Over voltage = 0.67 V

 Feed velocity= 0.75 mm/min (given to work in v direction)

Work material is copper with Z = 1, A = 63.57 and $\rho = 8.96$ g/cc

Electrolyte conductivity = $0.2 \Omega^{-1} \text{ cm}^{-1}$. (The symbols carry usual meaning)

- Determine the equation of the tool surface geometry. 12+8

 3. a) State the factors on which the depth of penetration of melting temperature in
 - EBM depends. Using Buckingham's \(\pi\$-theorem, find out an expression of the depth of penetration of melting temperature in EBM. \)
 b) For cutting 150 mm wide slot in a 1 mm thick tungsten sheet, an electron beam
 - machine with 5 kW power is used. For tungsten, the value of specific heat is 2.71 J/cm³-°C, thermal conductivity is 2.15 W/cm-°C and melting temperature is 3400 °C. Determine the speed of cutting.
- a) Explain the mechanics of EDM process.
 - b) During an electric discharge drilling of a 10 mm square hole in low carbon steel plate of 5 mm thickness, brass tool and kerosene are used. The resistance and the capacitance in relaxation circuit are 50 Ω and 10 μ F, respectively. The supply voltage is 200 V and the gap is maintained at such a value that the discharge (sparking) takes place at 150 V. Estimate the time required to complete the drilling operation.
 - Explain the inaccuracies introduced during EDM operation.
 7 + 7 + 6
- a) Discuss the model proposed by M.C.Shaw in connection with work material removal rate and also derive an expression for the same in USM.

6. a) With the help of a neat sketch explain the LAM process.
b) Discuss about high speed machining and hard machining.
c) What is deformation machining? Explain it.
5 + 10 + 5

7. a) Explain IBM process. Discuss about electrode characteristics, discharge mechanism, cathode electron emission and cathode sputtering.
b) Write the advantages and disadvantages of IBM process.
15 + 5

Show the variation of MRR with feeding force, frequency and amplitude in USM.

- 8. Write short notes on (any four): 5 x 4
 a) Peel grinding.
 - b) Ductile regime machining
 c) PAM
 d) WEDM
 - e) Tool electrode and dielectric fluids in EDM process.
 - f) Functions of electrolytes in ECM process.
 g) Abrasive slurry and tool material in USM.
 - h) Mechanics of EBM.

b)