

B.E. PRODUCTION ENGINEERING - SECOND YEAR - SECOND SEMESTER
INSPECTION AND PRODUCT CONTROL

Time : Three hours

Full marks: 100

Question No. 1 is compulsory. Answer any five from Question No. 2.

- 1.(a) While choosing an instrument for a specific measuring application, what are the characteristics need to be considered? (5×10)
 - (b) With real time examples, differentiate between interpolation and extrapolation methods of measurement.
 - (c) With a neat sketch, illustrate Indian standard for shaft and hole assembly.
 - (d) Mention about the advantages and disadvantages of having rough surface.
 - (e) Draw the cause and effect diagram for having excessive tapered jobs being produced during the turning operation.
 - (f) Between Cp and RPI, which one is more preferred and why? Provide some suggestions so as to increase the Cp value of a manufacturing process.
 - (g) For a rough surface, the values of 10 consecutive peaks and valleys are observed as follows (in μm). Determine the corresponding Rz value.
 Peaks: 1.2, 1.4, 2.5, 2.2, 3.3, 2.1, 3.4, 2.6, 3.0, 5.2
 Valleys: 1.1, 1.9, 2.0, 2.9, 3.2, 1.2, 3.8, 2.3, 3.4, 0.2
 - (h) How flatness and perpendicularity errors can be measured using a coordinate measuring machine?
 - (i) Differentiate between single- and double-ended snap gauges? What are the measures taken to reduce wear and tear in plug and ring gauges?
 - (j) What are the advantages and disadvantages of a mechanical-electrical type comparator?
- 2.(a) What a neat sketch, describe the working principle of any non-contact measuring instrument. (10×5)
 - (b) Write short notes on: (i) defect concentration diagram, (ii) merits and demerits of plug gauge.
 - (c) Describe how surface photographs help in evaluating roughness of a machined job. How would you differentiate between convex and concave surfaces based on their similar fringe patterns?
 - (d) Mention about different assignable causes which may present in any of the manufacturing processes. How would you minimize those assignable causes?
 - (e) Mention five areas of application of C chart. What are the limitations of X-bar and R charts?
 - (f) Two mating parts, A and B have an average clearance specified as 0.05 mm. Control charts indicate the standard deviation of the dimensions of A and B to be 0.02 mm and 0.03 mm respectively. Find the probability of interference between the two distributions. Assume the distributions to be normal. Given $\phi(-1.38696) = 0.0823$.
 - (g) Determine the GO and NOGO dimensions of standard gauges to control the production of 60 mm. shaft and hole pairs of H₈e₉ fit as per I.S. specifications given as below:
 (i) 60 mm. lies in the diameter step of 50 and 80 mm.
 (ii) Fundamental deviation of 'e' type shaft is $-11 D^{0.41}$
 (iii) Wear tolerance = 10% of the gauge tolerance.
 - (h) During measurement, what are the different sources of error? How would you minimize those errors?