

**B.E. MECHANICAL ENGINEERING THIRD YEAR SECOND SEMESTER - 2024**

**ADVANCED PRODUCTION PROCESSES**

Time: 3 hour

Full Marks: 100

Answer any *five* questions  
Assume suitable data if necessary.

1.
  - a) What is automation and production system?
  - b) Name and briefly define the different categories or level of production system.
  - c) Explain briefly three different manufacturing systems based on human participations.
  - d) Explain briefly three different automations.
  - e) What are the elements in open loop control system and closed loop control system?  
(2+4+6+6+2)

2. Derive the following expression for USM

$$Q \propto \frac{d^{\frac{3}{4}} F^{\frac{3}{4}} A^{\frac{3}{4}} C^{\frac{1}{4}}}{H_W^{\frac{3}{4}} (1+\lambda)^{\frac{3}{4}}} V$$

Notations bear usual meanings.

(20)

3.
  - a) Discuss the basic principle and general features of generative manufacturing processes
  - b) Explain the steriolithography with photo polymerization.
  - c) Discuss laminated object manufacturing process  
(6+7+7)
4.
  - a) What is micromanufacturing process? State the dimensional magnitudes of different micromanufacturing processes
  - b) Describe diamond micromachining process
  - c) What are the steps and sequences for micromachining using lithography?  
(5+10+5)
5.
  - a) Explain electron beam machining process
  - b) Explain laser beam machining process
  - c) What are the criteria for selecting electrode material in EDM?
  - d) What are the basic requirements of dielectric fluid in EDM?  
(8+8+2+2)

6. a) Differentiate between ECM and EDM processes. During an electric discharge drilling of 10-mm square hole in a low carbon steel plate of 5 mm thickness, brass tool and Kerosene is used. The resistance and capacitance in the relaxation circuit are  $50\ \Omega$  and  $10\ \mu\text{F}$ , respectively. The supply voltage is 200 volts and the gap is maintained at such a value that the discharge (sparking) takes place at 150 volts. Estimate the time required to complete the drilling operation.
- b) Discuss working principle of ECM process with necessary equations

(10+10)

7. a) What are the basic components of NC system
- b) State the difference between absolute vs. incremental positioning system in NC
- c) The part in below Fig.1 is to be drilled on a turret type drill press. The part is 15.0 mm thick. There are three drill sizes to be used: 8 mm, 10 mm, 12 mm. These drills are to be specified in the part program by tool turret positions T01, T02 and T03. All tooling is high speed steel. Cutting speed = 75 mm/min and feed = 0.08 mm/rev. Use the lower left corner of the part as origin in the x-y axis system. Write the part program in the word address format using absolute positioning. All the dimensions in Fig. are in mm.

(5+5+10)

